


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Frame and Underbody](#)
- 3. [Repair Instructions](#)
- 4.

Front Brake Rotor Cooling Extension Duct Replacement (J55)



[Click here for full size](#)
Front Bumper Fascia Energy Absorber Replacement

Callout	Component Name
Preliminary Procedure	
1	Retainer
2	Front Brake Rotor Cooling Extension Duct