


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Frame and Underbody
- 3. Repair Instructions
- 4.

Front End Lower Tie Bar Brace Replacement



[Click here for full size](#)
Tire and Wheel Removal and Installation

Fastener Caution.

Tighten

58N-m (43 lb ft)

Callout	Component Name
Preliminary Procedure	
1	Underbody Brace Bolt [2x]
	Caution:
	Refer to
2	Front End Lower Tie Bar Brace