


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Body Repair](#)
- 2. [Frame and Underbody](#)
- 3. [Repair Instructions](#)
- 4.

Rear Frame Heat Shield Replacement



[Click here for full size](#)
Rear Wheelhouse Liner Replacement - Left Side

- Rear Wheelhouse Liner Replacement - Right Side

Fastener Caution

Tighten

4.7N-m (42 lb in)

Callout	Component Name
Preliminary Procedure	
Remove the appropriate wheel house liner:	
•	
1	Rear Frame Heat Shield Bolt [2>x] Caution: Refer to
2	Clip
3	Rear Frame Heat Shield

