


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Frame and Underbody
- 3. Repair Instructions
- 4.

Rear Wheel Protective Bumper Replacement



Click here for full size
Rear Wheelhouse Liner Replacement - Left Side

•

Rear Wheelhouse Liner Replacement - Right Side

Fastener Caution

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
Remove the appropriate wheel house liner:	
•	
1	Rear Wheel Protective Bumper Bolt [3>x] Caution: Refer to
2	Rear Wheel Protective Bumper Procedure Disconnect any harness retainers.