


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Repair
- 2. Frame and Underbody
- 3. Repair Instructions
- 4.

Rear Wheelhouse Liner Replacement - Right Side



Click here for full size
Tire and Wheel Removal and Installation

- Rear Wheel Opening Molding Replacement

Fastener Caution

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedures	
1. Remove the right rear tire and wheel assembly.	
1	Rear Wheelhouse Liner Bolt [4>x] Caution: Refer to
2	Rear Wheelhouse Liner Screw [11x] Tighten 2.5N-m (22 lb in)
3	Retainer [2>x]
4	Rear Wheelhouse Liner