


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Fixed and Moveable Windows
- 3. Repair Instructions
- 4.

Front Side Door Window Weatherstrip Replacement (Coupe)



Click here for full size
Roof Lift Off Panel Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Front Side Door Window Weatherstrip Bolt Caution: Refer to
2	Front Side Door Window Weatherstrip Procedure Squeeze the weatherstrip and pull away from the roof lift off panel to remove.