


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Fixed and Moveable Windows
- 3. Repair Instructions
- 4.

Front Side Door Window Weatherstrip Retainer Replacement (Coupe)



[Click here for full size](#)
Front Side Door Window Weatherstrip Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
	Front Side Door Window Weatherstrip Retainer Bolt [4x]
1	Caution: Refer to
2	Front Side Door Window Weatherstrip Retainer