

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Fixed and Moveable Windows
- 3. Repair Instructions
- 4.

Rear Sliding Window Motor Cover Replacement

Click here for full size
Folding Top and Folding Top Stowage Compartment Lid Operation Warning.

Warning:

Refer to

Folding Top Stowage Compartment Lid Heat Warning.

Caution:

Refer to

Folding Top Guidelines Caution.

Preliminary Procedure

Operate the folding top stowage compartment lid to the fully open position.

Folding Top and Folding Top Stowage Compartment Lid Operation

Callout	Component Name
Warning:	
Refer to	
1	Rear Sliding Window Motor Cover
	Procedure
	Release the tab at the bottom of the rear sliding window motor cover.