


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Horns and Pedestrian Alerts
- 3. Repair Instructions
- 4.

Horn Replacement



[Click here for full size](#)
Front Compartment Front Panel Replacement

Fastener Caution .

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
1	Horn Bolt [2x] Caution: Refer to
2	Horn [2x] Procedure Disconnect the electrical connector.