


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. **Lighting**
- 3. Repair Instructions
- 4.

Front Floor Flood Lamp Replacement - Left Side



[Click here for full size](#)
Instrument Panel Lower Trim Panel Insulator Replacement - Left Side

Callout	Component Name
Preliminary Procedure	
1	Front Floor Flood Lamp Procedure 1. Rotate the lamp a quarter turn counterclockwise and remove. 2. Disconnect the electrical connector.