


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. **Lighting**
- 3. **Repair Instructions**
- 4.

Rear Body Structure Stop Lamp Replacement



[Click here for full size](#)
Rear Bumper Fascia Removal and Installation

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Rear Body Structure Stop Lamp Bolt [6x] Caution: Refer to
2	Rear Body Structure Stop Lamp Procedure Disconnect the electrical connector.