


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. **Lighting**
- 3. **Repair Instructions**
- 4.

Underhood Lamp Replacement



Click here for full size
Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
1	Underhood Lamp Bolt [2x]
	Caution:
	Refer to
2	Underhood Lamp
	Procedure
	Disconnect the electrical connector.