


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Vehicle Access
- 3. Repair Instructions
- 4.

Door Lock Switch Replacement - Driver Side



Click here for full size
Front Side Door Trim Replacement

- Reposition insulator, as required.

Callout	Component Name
Preliminary Procedures	
1.	
1	Door Lock Switch
	Procedure
	1. From the backside of the door trim panel, use a plastic trim tool to gently push in on the side tabs to release the switch from the front side door trim. 2. Disconnect the electrical connector.