


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Vehicle Access
- 3. Repair Instructions
- 4.

Front Side Door Inside Handle Cable Replacement



[Click here for full size](#)
Front Side Door Latch Replacement

Fastener Caution.

Tighten

9>N-m (80 lb in)

Preliminary Procedure	
Disconnect the handle cable from the front side door latch.	
	Front Side Door Inside Handle Bezel Finish Plug [2x]
1 Procedure	Use a suitable tool to remove the finish plugs from the handle.
	Front Side Door Inside Handle Screw [2x]
2 Caution:	
	Refer to

Front Side Door Inside Handle Cable

Note:

- 3 The handle and cable are replaced as an assembly and should not be separated.

Procedure

Reposition the carpet to gain access to the front side door inside handle cable.

mcx30.com