


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Vehicle Access
- 3. Repair Instructions
- 4.

Liftgate Latch Replacement



[Click here for full size](#)
Rear Compartment Lid Lock Cylinder Replacement

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
1	Rear Compartment Lid Latch Bolt [2x]
	Caution:
	Refer to

Callout	Component Name
2	Rear Compartment Lid Latch Procedure 1. Disconnect the electrical connector. 2. Release the auxiliary rear compartment latch release handle cable from the rear compartment latch.

mcx30.com