


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Vehicle Access
- 3. Repair Instructions
- 4.

Rear Compartment Lid Lock Cylinder Replacement



[Click here for full size](#)
Rear End Trim Cover Panel Replacement

Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
Preliminary Procedure	
1	Rear Compartment Lid Lock Cylinder Nut [3x] Caution: Refer to
2	Rear Compartment Lid Lock Cylinder Procedure Release the rear compartment lid lock cylinder cable from the rear compartment latch.