


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Body Systems
- 2. Vehicle Access
- 3. Repair Instructions
- 4.

Rear Compartment Lid Release Switch Replacement



[Click here for full size](#)
Front Side Door Trim Replacement

Callout	Component Name
Preliminary Procedure	
1	Rear Compartment Lid Release Switch Procedure 1. From the backside of the door trim panel, use a plastic trim tool to gently push in on the side tabs to release the switch from the front side door trim. 2. Disconnect the electrical connector.