

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Brakes**

2. **Hydraulic Brakes**

3. **Repair Instructions**

- 4.

Brake Master Cylinder Reservoir Filling

Warning:

Brake Fluid Irritant Warning

Caution:

Brake Fluid Effects on Paint and Electrical Components Caution

1. Visually inspect the brake fluid level through the brake master cylinder reservoir.
2. If the brake fluid level is at or below the half-full point during routine fluid checks, the brake system should be inspected for wear and possible brake fluid leaks.
3. If the brake fluid level is at or below the half-full point during routine fluid checks, and an inspection of the brake system did not reveal wear or brake fluid leaks, the brake fluid may be topped-off up to the maximum-fill level.
4. If the brake fluid level is above the half-full point, adding brake fluid is not recommended under normal conditions.
5. If brake system service was just completed, the brake fluid may be topped-off up to the maximum-fill level.
6. If brake fluid is to be added to the master cylinder reservoir, clean the outside of the reservoir on and around the reservoir cap prior to removing the cap and diaphragm.
7. Use only GM approved brake fluid from a clean, sealed brake fluid container to SLOWLY fill the brake master cylinder reservoir to avoid spillage due to overfilling.