


2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**


1. [Driver Information and Entertainment](#)
2. [Cellular, Entertainment, and Navigation](#)
3. [Repair Instructions](#)
- 4.

Communication Interface Module Bracket Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement




3.
[Click here for full size](#)

4. Remove the left windshield garnish molding (2). Windshield Garnish Molding Replacement




5.
[Click here for full size](#)

6. Remove the left instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement




7.
[Click here for full size](#)

8. Remove the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




9.
[Click here for full size](#)

10. Remove the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




11.
[Click here for full size](#)

12. Instrument Panel Knee Bolster (2) >> Remove - Instrument Panel Knee Bolster Replacement




13.
[Click here for full size](#)

14. Instrument Panel Lower Trim Panel Insulator - Left Side (2) >> Remove - Instrument Panel Lower Trim Panel Insulator Replacement - Left Side



15.
[Click here for full size](#)


16. Video Processing Module (1) >> Remove - Video Processing Module Replacement




17.
[Click here for full size](#)

18. Communication Interface Module Bracket Bolt (1) >> Remove [3x]
 19. Disconnect all electrical connectors.
 20. Communication Interface Module Bracket (2) >> Remove
 21. Transfer components as necessary.


Installation Procedure



1. [Click here for full size](#)
2. Connect the electrical connectors.
3. Communication Interface Module Bracket (2) >> Install
4. Caution:
Refer to Fastener Caution.
5. Communication Interface Module Bracket Bolt (1) Install and tighten [3x]2.5N-m (22 lb in)




6. [Click here for full size](#)
7. Video Processing Module (1) >> Install - Video Processing Module Replacement




8.
[Click here for full size](#)

9. Instrument Panel Lower Trim Panel Insulator - Left Side (2) >> Install - Instrument Panel Lower Trim Panel Insulator Replacement - Left Side




10.
[Click here for full size](#)

11. Instrument Panel Knee Bolster (2) >> Install - Instrument Panel Knee Bolster Replacement




12.
[Click here for full size](#)

13. Install the left instrument panel outer trim cover (1). Instrument Panel Outer Trim Cover Replacement




14.
[Click here for full size](#)

15. Install the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




16. [Click here for full size](#)

17. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



18. [Click here for full size](#)

19. Install the left windshield garnish molding (2).Windshield Garnish Molding Replacement



20.
[Click here for full size](#)

21. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement

mcx30.com