


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Driver Information and Entertainment
- 2. **Cellular, Entertainment, and Navigation**
- 3. **Repair Instructions**
- 4.

Navigation Signal Splitter Replacement



[Click here for full size](#)
Driver Footrest Bracket Replacement

Fastener Caution.

Procedure

- 1. Remove the top splitter nut and plastic bracket mounting bolt.
- 2. Reposition the plastic bracket.
- 3. Remove the lower splitter nut
- 4. Disconnect the electrical connector.

Tighten

3 N-m (27 lb in)

Callout	Component Name
Preliminary Procedure	
1	Navigation Signal Splitter Nut [2x] Caution: Refer to

Callout	Component Name
2	Navigation Signal Splitter

mcx30.com