


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Driver Information and Entertainment
- 2. **Cellular, Entertainment, and Navigation**
- 3. Repair Instructions
- 4.

Radio Antenna Module Replacement



[Click here for full size](#)
Quarter Outer Panel Replacement - Left Side

Callout	Component Name
Preliminary Procedure	
1	Fuel Tank Filler Pipe Ground Bolt [2>x] Tighten 22N-m (16 lb ft)
2	Radio Antenna Module Procedure 1. Disconnect the electrical connector. 2. Release the retaining tabs.