


2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**


1. [Driver Information and Entertainment](#)
2. [Cellular, Entertainment, and Navigation](#)
3. [Repair Instructions](#)
- 4.

Radio Front Center Speaker Grille Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the right body hinge pillar garnish molding (1). [Body Hinge Pillar Garnish Molding Replacement](#)




3. [Click here for full size](#)

4. Remove the right windshield garnish molding (2). Windshield Garnish Molding Replacement




5. [Click here for full size](#)

6. Remove the right instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



7.
[Click here for full size](#)

8. Remove the right radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




9.
[Click here for full size](#)


10. Using a flat-bladed plastic trim tool, release the retaining clips.

11. Release the forward tabs by pulling the radio front center speaker grille (1) rearward.


Installation Procedure




1.
Click here for full size
2. Radio Front Center Speaker Grille (1) >> Install




3.
Click here for full size
4. Install the right radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement



5. [Click here for full size](#)
6. Install the right instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



7. [Click here for full size](#)
8. Install the right windshield garnish molding (2).Windshield Garnish Molding Replacement



9.
[Click here for full size](#)

10. Install the right body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement

mcx30.com