


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Driver Information and Entertainment
- 2. **Cellular, Entertainment, and Navigation**
- 3. **Repair Instructions**
- 4.

Radio Front Side Door Speaker Replacement



[Click here for full size](#)
Front Side Door Trim Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Radio Front Side Door Speaker Bolt [4x] Caution: Refer to
2	Radio Front Side Door Speaker Procedure Disconnect the electrical connector.