


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Driver Information and Entertainment
- 2. **Cellular, Entertainment, and Navigation**
- 3. Repair Instructions
- 4.

Radio Front Side Door Upper Speaker Grille Replacement



[Click here for full size](#)
Radio Front Side Door Upper Speaker Replacement

Fastener Caution.

Tighten

1.2 N-m (11 lb in)

Callout	Component Name
Preliminary Procedure	
1	Radio Front Side Door Upper Speaker Grille Bolt [11x] Caution: Refer to
2	Radio Front Side Door Upper Speaker Grille Procedure 1. Disconnect the electrical connector. 2. Transfer components as necessary.