


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Driver Information and Entertainment](#)
- 2. [Cellular, Entertainment, and Navigation](#)
- 3. [Repair Instructions](#)
- 4.

Radio Front Side Door Upper Speaker Replacement



[Click here for full size](#)
Front Side Door Trim Replacement

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1	Radio Front Side Door Upper Speaker Bolt [2x] Caution: Refer to
2	Radio Front Side Door Upper Speaker Procedure Disconnect the electrical connector.