


2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**


1. [Driver Information and Entertainment](#)
2. [Cellular, Entertainment, and Navigation](#)
3. [Repair Instructions](#)
- 4.

Radio Front Speaker Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement




3.
[Click here for full size](#)

4. Remove the left windshield garnish molding (2). Windshield Garnish Molding Replacement



5.
[Click here for full size](#)


6. Remove the left instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement




7. [Click here for full size](#)
8. Radio Front Speaker Bolt (1) >> Remove [2x]
9. Disconnect the electrical connector.
10. Radio Front Speaker (2) >> Remove

Installation Procedure

1. Connect the electrical connector.




2. [Click here for full size](#)
3. Radio Front Speaker (2) >> Install
4. Caution:
Refer to Fastener Caution.
5. Radio Front Speaker Bolt (1) >> Install and tighten [2x]2.5N-m (22 lb in)




6. [Click here for full size](#)

7. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



8. [Click here for full size](#)

9. Install the left windshield garnish molding (2).Windshield Garnish Molding Replacement



10.
[Click here for full size](#)

11. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement

mcx30.com