


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Driver Information and Entertainment
- 2. **Cellular, Entertainment, and Navigation**
- 3. **Repair Instructions**
- 4.

Radio Replacement



[Click here for full size](#)
Instrument Panel Lower Trim Panel Insulator Replacement - Right Side

Control Module References

Callout	Component Name
Preliminary Procedure	
1	Radio Procedure 1. Disconnect and reposition harness as necessary. 2. Release the retaining tabs. 3. Perform the necessary programming and setup procedure: