


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Driver Information and Entertainment
- 2. **Cellular, Entertainment, and Navigation**
- 3. **Repair Instructions**
- 4.

Radio Speaker Amplifier Replacement



[Click here for full size](#)
Vehicle Performance Data Recorder Bracket Replacement

Fastener Caution

Tighten

6>N-m (53 lb in)

Control Module References

Callout	Component Name
Preliminary Procedure	
1>	Radio Speaker Amplifier Nut [3>x] Caution :
2>	Radio Speaker Amplifier Procedure Perform the necessary programming and setup procedure: