

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. **Driver Information and Entertainment**
2. **Cellular, Entertainment, and Navigation**
3. **Repair Instructions**
- 4.

Radio Volume Switch Replacement

Click here for full size

Steering Wheel Shroud Replacement

- Disconnect the electrical connector.

Fastener Caution.

Tighten

1 N-m (9 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Radio Volume Switch Bolt [2x]
	Caution:
	Refer to
2	Radio Volume Switch