


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Driver Information and Entertainment
- 2. Displays and Gauges
- 3. Repair Instructions
- 4.

Head-Up Display Replacement



[Click here for full size](#)
Instrument Panel Carrier Replacement

•

Side Window Defogger Outlet Duct Replacement - Left Side

Fastener Caution.

Tighten

2.5N-m (22 lb in)

Callout	Component Name
Preliminary Procedure	
1.	
1	Head-Up Display Bolt [4x]
	Caution: Refer to
2	Head-Up Display
	Procedure Disconnect the electrical connectors.