


2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**


1. **Driver Information and Entertainment**
2. **Displays and Gauges**
3. **Repair Instructions**
- 4.

Head-Up Display Switch Replacement

Removal Procedure




1. [Click here for full size](#)
2. Remove the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement




3.
[Click here for full size](#)

4. Remove the left windshield garnish molding (2). Windshield Garnish Molding Replacement




5.
[Click here for full size](#)

6. Remove the left instrument panel trim pad radio speaker opening cover (1). Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement




7.
[Click here for full size](#)

8. Remove the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




9.
[Click here for full size](#)

10. Remove the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement



11.
[Click here for full size](#)


12. Instrument Panel Knee Bolster (2) >> Remove - Instrument Panel Knee Bolster Replacement




13.
[Click here for full size](#)

14. Release the tabs of the head-up display switch (1) from the instrument panel switch trim plate.


Installation Procedure



1. [Click here for full size](#)
2. Install the head-up display switch (1) to the instrument panel switch trim plate.




3. [Click here for full size](#)
4. Instrument Panel Knee Bolster (2) >> Install - Instrument Panel Knee Bolster Replacement




5. [Click here for full size](#)

6. Install the left instrument panel outer trim cover (1).Instrument Panel Outer Trim Cover Replacement




7. [Click here for full size](#)

8. Install the left radio front speaker grille molding (2).Radio Front Speaker Grille Molding Replacement




9.
[Click here for full size](#)

10. Install the left instrument panel trim pad radio speaker opening cover (1).Instrument Panel Trim Pad Radio Speaker Opening Cover Replacement



11.
[Click here for full size](#)

12. Install the left windshield garnish molding (2).Windshield Garnish Molding Replacement



13.
[Click here for full size](#)

14. Install the left body hinge pillar garnish molding (1).Body Hinge Pillar Garnish Molding Replacement

mcx30.com