


2022 CHEVROLET CORVETTE SERVICE MANUAL

- [SEARCH](#)


1. [Driver Information and Entertainment](#)
2. [Image Display Cameras](#)
3. [Repair Instructions](#)
- 4.

Video Processing Module Replacement


Removal Procedure




1. [Click here for full size](#)
2. Instrument Panel Knee Bolster (2) >> Remove - Instrument Panel Knee Bolster Replacement



3. [Click here for full size](#)
4. Instrument Panel Lower Trim Panel Insulator - Left Side (2) >> Remove - Instrument Panel Lower Trim Panel Insulator Replacement - Left




5. [Click here for full size](#)
6. Video Processing Module Bracket Bolt (1) >> Remove
7. Disconnect the electrical connectors.




8. [Click here for full size](#)
9. Tilt the bottom of the video processing module (1) forward to release from the bracket.
10. Video Processing Module (1) >> Remove


Installation Procedure



1. [Click here for full size](#)
2. Tilt the bottom of the video processing module (1) forward to engage to the bracket.
3. Video Processing Module (1) >> Install
4. Connect the electrical connectors.




5. [Click here for full size](#)
6. Caution:
Refer to Fastener Caution.
7. Video Processing Module Bracket Bolt (1) >> Install and tighten 9>N-m (80 lb in)



8.
[Click here for full size](#)

9. Instrument Panel Lower Trim Panel Insulator - Left Side (2) >> Install - Instrument Panel Lower Trim Panel Insulator Replacement - Left Side



10.
[Click here for full size](#)

11. Instrument Panel Knee Bolster (2) >> Install - Instrument Panel Knee Bolster Replacement

12. Perform the necessary programming and setup procedure: Control Module References