


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Engine/Propulsion](#)
- 2. [Engine Controls and Fuel - 6.2L \(LT2\)](#)
- 3. [Repair Instructions](#)
- 4.

Accelerator Pedal Replacement



Click here for full size
Fastener Caution.

Tighten

9>N-m (80 lb in)

Callout	Component Name
1	Accelerator Pedal Cover
2	Accelerator Pedal Bracket Bolt
	Caution: Refer to