


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Engine/Propulsion](#)
- 2. [Engine Controls and Fuel - 6.2L \(LT2\)](#)
- 3. [Repair Instructions](#)
- 4.

Camshaft Position Sensor Replacement



[Click here for full size](#)
[Engine Oil Tank Replacement](#)

Fastener Caution.

Tighten

8.5N-m (75 lb in)

Callout	Component Name
Preliminary Procedure	
1	Camshaft Position Sensor Bracket Bolt Caution: Refer to
2	Camshaft Position Sensor Procedure Disconnect the electrical connector.