


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Crankshaft Position Sensor Replacement



[Click here for full size Starter Replacement](#)

Fastener Caution.

Tighten

25N-m(18 lb ft)

Crankshaft Position Variation Learn

Callout	Component Name
Preliminary Procedure	
1	Crankshaft Position Sensor Bolt Caution: Refer to
2	Crankshaft Position Sensor Procedure 1. Disconnect the electrical connector. 2. Perform the crankshaft position variation learn.