


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Engine Oil Temperature Sensor Replacement



[Click here for full size](#)
Rear Cradle Shear Plate Replacement

Component Fastener Tightening Caution.

Procedure

Disconnect the electrical connector.

Tighten

20N-m (15 lb ft)

Callout	Component Name
Preliminary Procedure	
1	Engine Oil Temperature Sensor
	Caution:
	Refer to