


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Fuel Feed and Evaporative Emission Pipe Replacement - Left Side



Click here for full size
Diesel/Gasoline Vapors Warning.

Warning:

Refer to

Safety Glasses Warning.

Preliminary Procedure

Fuel Tank Replacement - Left Side

Plastic Collar Quick Connect Fitting Service

Callout	Component Name
Warning:	
Refer to	
1	Fuel Feed and Evaporative Emission Pipe
	Procedure
	Disconnect the quick connect fitting and remove from retainer.