


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

1. Engine/Propulsion
2. Engine Controls and Fuel - 6.2L (LT2)
3. Repair Instructions
- 4.

Fuel Feed Front Hose Replacement



Click here for full size
Diesel/Gasoline Vapors Warning.

Warning:

Refer to

Safety Glasses Warning.

Preliminary Procedures

1. Relieve the fuel system pressure.

Fuel Pressure Relief

- Disconnect the battery negative cable.

Battery Negative Cable Disconnection and Connection

-

Underbody Rear Air Deflector Replacement

Fastener Caution.

Tighten

9>N-m (80 lb in)

Metal Collar Quick Connect Fitting Service

- Check for fuel leaks.

Callout	Component Name
Warning:	
Refer to	
1	Fuel Feed Front Hose Clip Bolt Caution: Refer to
2	Fuel Feed Front Hose Procedure 1. Disconnect the quick connect fittings.

mcx30.com