


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Fuel Feed Front Pipe Bracket Replacement



[Click here for full size](#)
Underbody Rear Air Deflector Replacement

- Remove fuel feed pipe retainer from bracket.
- Remove all wiring harness retainers from bracket.

Fastener Caution.

Tighten

22N-m (16 lb ft)

Callout	Component Name
Preliminary Procedures	
1.	
1	Fuel Feed Front Pipe Clip Bolt
	Caution:
	Refer to
2	Fuel Feed Front Pipe Bracket