


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Fuel Feed Pipe Replacement (Coupe)



Click here for full size
Fuel Pressure Relief

•

Fuel Pump Insulator Replacement

Fastener Caution.

Tighten

10N-m (89 lb in)

Metal Collar Quick Connect Fitting Service

Callout	Component Name
Preliminary Procedures	
1.	
1	Fuel Feed Pipe Bolt
	Caution:
	Refer to

Callout	Component Name
2	Fuel Feed Pipe
	Procedure
	Disconnect the fuel feed pipe metal collar fittings.

mcx30.com