


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Fuel Injector Wiring Harness Replacement



Click here for full size
Fuel Pump Insulator Replacement

- Disconnect the electrical connectors.

Callout	Component Name
Preliminary Procedures	
1.	
1	Fuel Injector Wiring Harness
	Procedure
	Disconnect and remove the wiring harness from the fuel rail.