

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Engine/Propulsion](#)
- 2. [Engine Controls and Fuel - 6.2L \(LT2\)](#)
- 3. [Repair Instructions](#)
- 4.

Fuel Pump Insulator Replacement (Convertible)

[Click here for full size](#)
[Intake Manifold Replacement](#)

Callout	Component Name
Danger: The noise cancelling foam component MUST be replaced if it has been exposed to engine fluids. Failure to replace the noise cancelling foam component that has been exposed to engine fluids may result in an engine fire resulting in catastrophic engine damage, and possible injury or death. Preliminary Procedure	
1	Fuel Pump Insulator