


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Fuel Pump Power Control Module Replacement



Click here for full size
Rear Wheelhouse Liner Replacement - Left Side

Fastener Caution.

Tighten

9>N-m (80 lb in)

K111 Fuel Pump Power Control Module Configuration

- Perform the exhaust flow control valve learn.

Exhaust Flow Control Valve Learn

Callout	Component Name
Preliminary Procedure	
1	Fuel Pump Power Control Module Nut [3>x]
	Caution:
	Refer to

Callout	Component Name
2	Fuel Pump Power Control Module Procedure 1. Disconnect the electrical connector. 2. Perform the fuel pump power control module configuration.

mcx30.com