


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Fuel Tank Filler Evaporative Emission Pipe Replacement



Click here for full size
Diesel/Gasoline Vapors Warning.

Warning:

Refer to

Safety Glasses Warning.

Preliminary Procedure

Engine Cooling Fan Bracket Replacement - Left Side

Plastic Collar Quick Connect Fitting Service

Callout	Component Name
Warning:	
Refer to	
1	Fuel Tank Filler Evaporative Emission Pipe
	Procedure
	Disconnect the quick connect fittings.