

2022 CHEVROLET CORVETTE SERVICE MANUAL

- **SEARCH**

1. Engine/Propulsion
2. Engine Controls and Fuel - 6.2L (LT2)
3. Repair Instructions
- 4.

Heated Oxygen Sensor Heater Resistance Learned Values Reset

Diagnostic Instructions

- Perform the Diagnostic System Check prior to using this diagnostic procedure: Diagnostic System Check - Vehicle
- Review the description of Strategy Based Diagnosis: Strategy Based Diagnosis

Description

This procedure resets the control module learned values of the component/system: B52 Heated Oxygen Sensor - Resistance

When to Perform the Procedure

Note :

Failure to perform this procedure may result in poor system performance, DTCs being set, or customer dissatisfaction.

Perform this procedure when the following component has been serviced: B52 Heated Oxygen Sensor - Replaced

Conditions for Running the Procedure

Ignition Switch = Run/Crank

Reference Information

Scan Tool Reference

Control Module References

With Scan Tool

1. Ignition >> On / Vehicle >> In Service Mode
2. Select: Module Diagnostics
3. Select: Engine Control Module
4. Select: Configuration/Reset Functions
5. Select: Reset Functions
6. Select: Heated Oxygen Sensor Heater Resistance Learned Values Reset
7. Note :

The scan tool does not display the learn/reset status.

8. Follow the instructions on the scan tool. - The procedure will complete within 10 s
9. All OK.

Repair Instructions

Perform the Diagnostic Repair Verification after completing the repair: Diagnostic Repair Verification