


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Ignition Coil Bracket Replacement - Left Side



[Click here for full size](#)
Ignition Coil Wire Replacement - Left Side

•

Ignition Coil Replacement - Left Side

Fastener Caution.

Tighten

25N-m (18 lb ft)

Callout	Component Name
Preliminary Procedures	
1.	
1	Ignition Coil Bracket Bolt [2>x]
	Caution: Refer to
2	Ignition Coil Bracket [2>x]