


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Ignition Coil Replacement - Left Side



[Click here for full size](#)
Spark Plug Wire Replacement - Left Side

Fastener Caution.

Tighten

5>N-m (44 lb in)

Callout	Component Name
Preliminary Procedure	
1	Ignition Coil Bolt [2>x] Caution: Refer to
2	Ignition Coil Procedure Disconnect the electrical connector from the ignition coil.