


# 2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

## Ignition Coil Replacement - Right Side



[Click here for full size](#)  
Spark Plug Wire Replacement - Right Side

Fastener Caution.

Tighten

5>N-m (44 lb in)

| Callout               | Component Name                                                                                    |
|-----------------------|---------------------------------------------------------------------------------------------------|
| Preliminary Procedure |                                                                                                   |
| 1                     | Ignition Coil Bolt [2>x]<br><br>Caution:<br><br>Refer to                                          |
| 2                     | Ignition Coil<br><br>Procedure<br><br>Disconnect the electrical connector from the ignition coil. |