


2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. Engine/Propulsion
- 2. Engine Controls and Fuel - 6.2L (LT2)
- 3. Repair Instructions
- 4.

Ignition Coil Wire Replacement - Left Side



Click here for full size
Rear Cradle Shear Plate Replacement

- Disconnect the electrical connectors.
- Ignition Coil Bracket Bolt @ Ignition Coil Bracket >> Remove [2>x] -

Ignition Coil Bracket Replacement - Left Side

Fastener Caution.

Tighten

5>N-m (44 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Ignition Coil Bracket Bolt [2>x]
	Caution:
	Refer to

Callout	Component Name
2	Ignition Coil Wire [2>x]
	Procedure
	Disconnect the electrical connectors from the ignition coils.

mcx30.com