

2022 CHEVROLET CORVETTE SERVICE MANUAL

- SEARCH

- 1. [Engine/Propulsion](#)
- 2. [Engine Controls and Fuel - 6.2L \(LT2\)](#)
- 3. [Repair Instructions](#)
- 4.

Manifold Absolute Pressure Sensor Replacement (Convertible)

Click here for full size
Rear Window Panel Replacement

- Disconnect the electrical connector.

Fastener Caution.

Tighten

4.5N-m (40 lb in)

Callout	Component Name
Preliminary Procedures	
1.	
1	Manifold Absolute Pressure Sensor Bolt Caution: Refer to
2	Manifold Absolute Pressure Sensor